

Lessons learned from one of New Zealand's most challenging civil engineering projects: rebuilding the earthquake damaged pipes, roads, bridges and retaining walls in the city of Christchurch 2011 - 2016.

Seismically Induced Shear of a Concrete Reservoir in the February 2011 Christchurch Earthquake: Investigations and Response

Story: Huntsbury Reservoir

Theme: Design

A PowerPoint presentation prepared for the Australia New Zealand Geotechnical Engineering Conference.

This document has been provided as an example of a tool that might be useful for other organisations undertaking complex disaster recovery or infrastructure rebuild programmes.

For more information about this document, visit www.scirtlearninglegacy.org.nz



This work is licensed under a [Creative Commons Attribution 3.0 New Zealand License](#).

The authors, and Stronger Christchurch Infrastructure Rebuild Team (SCIRT) have taken all reasonable care to ensure the accuracy of the information supplied in this legacy document. However, neither the authors nor SCIRT, warrant that the information contained in this legacy document will be complete or free of errors or inaccuracies. By using this legacy document you accept all liability arising from your use of it. Neither the authors nor SCIRT, will be liable for any loss or damage suffered by any person arising from the use of this legacy document, however caused.

Seismically Induced Shear of a Concrete Reservoir in the February 2011 Christchurch Earthquake: Investigations and Response

ANZ 2015 // 22-25 February 2015

Marcus Gibson – Associate Geotechnical Engineer Beca Ltd / SCIRT

Co-author: Ann Williams – Technical Director - Engineering Geology, Beca Ltd



Huntsbury No. 1 Reservoir

- Circa 1954
- 36,000 m³ capacity
- Reinforced concrete
- M_w 6.2 EQ 22 February 2011
- Damage → complete functional failure



Canterbury Earthquake Sequence



Huntsbury No. 1 Reservoir




Structural Damage



Crack Mapping

- Zone 20-25 m wide
- Oriented 280° - 300°
- Full depth of slab
- S moved ~ 50 mm NW



Tunnel Observations











Observations Beyond the Reservoir



Geotechnical Investigation

Legend


-  Floor Cracks
-  Borehole
-  Trench
-  Evidence of shear zone within core
-  Evidence of shear zone within trenches
-  Evidence of shear zone within Tunnel
-  Significant core loss



Geotechnical Investigation



Interpreted cross-section of shear zone











Assessment of Geological Risk


- Expect further displacement during seismic events
- Not possible to forecast seismic events or movement.
- Potential 50-150mm of movement along shear zone over next 50 years
- Extent and width of shear zone 20-25m
- Principles of MfE 'Planning for Development of Land on or Close to Active Faults'

- Alternative site – not viable
- Reinstatement solutions:
 - Option A: Reinstatement existing
 - Option B: Single new reservoir
 - Option C: Multiple new reservoirs
- Considered a range of technical solutions
- Materials: Reinforced Concrete Steel, HDPE liner

Selected Repair Solution

Legend

-  Floor Cracks
-  Borehole
-  Trench
-  Evidence of shear zone within core
-  Evidence of shear zone within trenches
-  Evidence of shear zone within Tunnel
-  Significant core loss
-  New Structures



Construction



Completed Repair



Conclusions

- Observations and investigation confirmed presence of 20-25m wide previously unknown shear zone
- Geotechnical design criteria - based on recorded evidence and judgement
- Assessment of risk, site viability and technical solutions
- Solution: modification of existing structure providing setback
- Highlights importance of integrated engineering, geological and geotechnical assessments when designing critical infrastructure.

